

# UTAH STATE CAPITOL ARCHITECTURE: EXTERIOR SURVEY REPORT

ELEVATION LOCATION: LOWER DRUM

Survey Date: 4/26/00

**Code:** EX-028

**Description:** Drum wall


**Location:** North Elevation

**Grid:** H/E 52; H/W 51

**Condition:** CR

Cracked element

**Comments:**



**Code:** EX-028

**Description:** Drum wall

**Location:** North Elevation

**Grid:** I

**Condition:** BR

Broken, severely cracked or chipped

**Comments:**



**Code:** EX-028

**Description:** Drum wall

**Location:** North Elevation

**Grid:** J/I, E 5

**Condition:** PAT

Poor quality, non-matching patch

**Comments:**



**Code:** EX-028

**Description:** Drum wall

**Location:** North Elevation



**Grid:** I/E 7

**Condition:** J

Mortar joint with missing or loose mortar

**Comments:**



**Code:** EX-028**Description:** Drum wall**Location:** North Elevation above door**Grid:** J/I, CL**Condition:** STSignificant Staining; may  
indicate rusted connector**Comments:****Code:** EX-028**Description:** Drum wall**Location:** North Elevation**Grid:** H/E 15, W-15**Condition:** INTIntrusive, non-original, non-  
essential element**Comments:** pipe bracket**Code:** EX-028**Description:** Drum wall**Location:** North Elevation**Grid:** H/typical**Condition:** INTIntrusive, non-original, non-  
essential element**Comments:** metal anchor, screws for lights**Code:** EX-028**Description:** Drum wall**Location:** South Elevation at pipe**Grid:****Condition:** NONon-original, incompatible but  
essential elements**Comments:**

**Code:** EX-028

**Description:** Drum wall

**Location:** East Elevation

**Grid:** H typical

**Condition:** CR

Cracked element

**Comments:**



**Code:** EX-028

**Description:** Drum wall

**Location:** East Elevation

**Grid:** I/S 4, S 7, S 19; J/L 19, L 18

**Condition:** J

Mortar joint with missing or loose mortar

**Comments:**



**Code:** EX-028

**Description:** Drum wall

**Location:** East Elevation

**Grid:** I/S 4

**Condition:** CR

Cracked element

**Comments:**



**Code:** EX-028

**Description:** Drum wall

**Location:** East Elevation

**Grid:** I/N 22, H/N 48, H/S 48

**Condition:** CR

Cracked element

**Comments:**



**Code:** EX-028

**Description:** Drum wall

**Location:** East Elevation

**Grid:** I/N 3, I/N 30..

**Condition:** BR

Broken, severely cracked or  
chipped

**Comments:**



**Code:** EX-028

**Description:** Drum wall

**Location:** East elevation

**Grid:** H/S-50, N-50

**Condition:** CR

Cracked element

**Comments:** CR--12"



**Code:** EX-028

**Description:** Drum wall

**Location:** East elevation

**Grid:** I/S-10

**Condition:** CR

Cracked element

**Comments:** CR



**Code:** EX-028

**Description:** Drum wall


**Location:** East elevation

**Grid:** I/S-19, S-7

**Condition:** J

Mortar joint with missing or loose  
mortar

**Comments:** J





**Code:** EX-029

**Description:** Drum cornice


**Location:** North Elevation

**Grid:** J/E 25; J/CL

**Condition:** BR

Broken, severely cracked or  
chipped

**Comments:**



**Code:** EX-029

**Description:** Drum cornice


**Location:** North Elevation

**Grid:** J/E 25

**Condition:** J

Mortar joint with missing or loose  
mortar

**Comments:** (typ) E-21, W-7, W-15, U-26



**Code:** EX-029

**Description:** Drum cornice

**Location:** North Elevation

**Grid:** J/E 12, E 7

**Condition:** CR

Cracked element

**Comments:**



**Code:** EX-029

**Description:** Drum cornice

**Location:** North Elevation

**Grid:** I, typical

**Condition:** J

Mortar joint with missing or loose  
mortar

**Comments:**



**Code:** EX-029

**Description:** Drum cornice

**Location:** North Elevation

**Grid:** J/CL to W 25

**Condition:** BR

Broken, severely cracked or  
chipped

**Comments:** all the way around: South, 7  
breaks; East, 4.



**Code:** EX-029

**Description:** Drum cornice

**Location:** East Elevation

**Grid:** I/S 49

**Condition:** CR

Cracked element

**Comments:**



**Code:** EX-029

**Description:** Drum cornice

**Location:** East Elevation

**Grid:** J/S 25, S19

**Condition:** BR

Broken, severely cracked or  
chipped

**Comments:**



**Code:** EX-029

**Description:** Drum cornice


**Location:** East Elevation

**Grid:** J/N 4

**Condition:** J, CK

Mortar joint damage, covered  
poorly with caulking

**Comments:**



**Code: EX-029****Description: Drum cornice****Location:** West Elevation**Grid:** I/N 50**Condition:** CR

Cracked element

**Comments:****Code: EX-030****Description: Drum balustrade****Location:** East Elevation**Grid:** J/typical**Condition:** J

Mortar joint with missing or loose mortar

**Comments:** expansion joint**Code: EX-037****Description: Window trim****Location:** East Elevation**Grid:** J/typical**Condition:** P

Paint missing or damaged

**Comments:** peeling**Code: EX-039****Description: Entablature****Location:** East Elevation**Grid:** L/S 4, N 4**Condition:** BR

Broken, severely cracked or chipped

**Comments:**



**Code:** EX-039

**Description:** Entablature

**Location:** West Elevation

**Grid:** L/N 15, N 6, S 10, S 15

**Condition:** ST

Significant Staining; may  
indicate rusted connector

**Comments:** (yellow)



**Code:** EX-040

**Description:** Cornice


**Location:** North Elevation

**Grid:** L

**Condition:** J, ST

Mortar joint damage and  
significant staining

**Comments:** J typical; ST: E-7, W-7.



**Code:** EX-040

**Description:** Cornice


**Location:** South Elevation

**Grid:** L/W 21 and W 7

**Condition:** ST

Significant Staining; may  
indicate rusted connector

**Comments:**



**Code:** EX-040

**Description:** Cornice

**Location:** West Elevation

**Grid:** L/S 33

**Condition:** CR

Cracked element

**Comments:**





**Code:** EX-041

**Description:** Balustrade

**Location:** West Elevation

**Grid:** J/ typical

**Condition:** BR

Broken, severely cracked or  
chipped

**Comments:** chipped; small chips typical



**Code:** EX-077

**Description:** Mechanical grille

**Location:** North Elevation

**Grid:** I/E 15

**Condition:** O

Other (describe)

**Comments:** paint on metal; also stain at bottom



**Code:** EX-083

**Description:** Flashing

**Location:** North Elevation

**Grid:** I/E 40

**Condition:** BR

Broken, severely cracked or  
chipped

**Comments:** protruding



**Code:** EX-090

**Description:** Door

**Location:** South Elevation

**Grid:** I/CL

**Condition:** MT

Metal damage

**Comments:** rusted hinges (new)

